

## **APPENDIX E-8B**

### **REPRESENTATIVE KOP PHOTOGRAPHS—OPERATIONS**



**K5: J.C. BOYLE RESERVOIR FROM PIONEER PARK EAST—HIGH POOL CONDITIONS**



**K5: J.C. BOYLE RESERVOIR FROM PIONEER PARK EAST—LOW POOL CONDITIONS**



J.C. BOYLE RESERVOIR AT MAINTENANCE DRAWDOWN CONDITIONS (VIEW 1)



J.C. BOYLE AT MAINTENANCE DRAWDOWN CONDITIONS (VIEW 2)





**BB2: KLAMATH RIVER FROM BRIDGE BELOW J. C. BOYLE DAM**

**Upstream**



**Waterflow**

**Low:  
100 cfs**

**Downstream**



**Medium:  
775 cfs**



**High:  
1,350 cfs**





**BB5: J.C. BOYLE BYPASS REACH VIEW #2 FROM ACCESS ROAD**

**Waterflow**

**Looking Upstream**

**Low:  
325 cfs**



**Medium:  
700 cfs**



**High:  
1,575 cfs**





**HC6: KLAMATH RIVER (CALDERA RAPIDS) FROM FRAIN RANCH**

**Upstream**



**Waterflow**

**Low:  
350 cfs**

**Medium:  
1,700 cfs**

**High:  
2,800 cfs**

**Downstream**





**C1: COPCO LAKE FROM MALLARD COVE RECREATION AREA—HIGH POOL CONDITIONS**



**C1: COPCO LAKE FROM MALLARD COVE RECREATION AREA—LOW POOL CONDITIONS**





**IG5: IRON GATE RESERVOIR FROM MIRROR COVE RECREATION AREA—HIGH POOL CONDITIONS**



**IG5: IRON GATE RESERVOIR FROM MIRROR COVE RECREATION AREA—LOW POOL CONDITIONS**



**IG7: IRON GATE RESERVOIR FROM LONG GULCH RECREATION AREA—HIGH POOL CONDITIONS**



**IG7: IRON GATE RESERVOIR FROM LONG GULCH RECREATION AREA—LOW POOL CONDITIONS**





**IG12: KLAMATH RIVER FROM IRON GATE HATCHERY RIVER ACCESS**

**Upstream**

**Waterflow**


**Downstream**



**Low:  
760 cfs**



**Medium:  
1,350 cfs**



**High:  
1,770 cfs**





**BG3: KLAMATH RIVER FROM TREE OF HEAVEN RIVER ACCESS BOAT RAMP**

**Upstream**

**Waterflow**

**Downstream**



**Low:  
760 cfs**



**Medium:  
1,350 cfs**



**High:  
1,770 cfs**

