PACIFICORP

PROTECTION AND CONTROL RELAY EQUIPMENT MEMORANDUM FORM

Version 13

PacifiCorp Relay Technical Services Form PCF-EQP-MEMO

Refer to PacifiCorp Procedure PCP-EQP-MEMO

The person responsible for the completion of this form shall print their name below as verification that the form has been filled out accurately.

Responsible Person: EDWARDS **Phone number:** 541-864-9885 **Date:** 11/22/2022

Equipment Identification

Substation: WALKER BRYAN	Work Order: 10069498	Relay Package SAP #: 380318
Apparatus Equipment/Line Protected: ETNA FEEDER 5G41	Bldg/Equip Physical Location: CB_5G41	Recloser Controller Battery SI#: 1005041

Update to Existing Package: ☑	New Package/Upgrade Installation: ☐	CIPS Firmware Update: ☐ *Send to cipmaintrecord@pacificorp.com	Non-CIPS Firmware Update: ☐ *Rocky Mountain Power: Send to RMPAssetmanagement@pacificorp.com *Pacific Power: Send to PP_EquipmentMemorandums@pacificorp.com

Relay Equipment Installed

SAP #	IEEE #	CIPS	Panel #	Manufacturer	Type	Part #	Serial #	Firmware #	Pswd Change	Alm to SCADA	Load Shed	Ext Conn	CIP Sticker	Security Log	Dwgs Chkd
437522	11	None	5G41	SEL	751	"PARTNO=751502BA06XBB850330","06AD"	Sn#3203040002	"FID=SEL-751-R301-V1-Z009005-D20220308","08AC"	☑	☐	☑		☐	☐	☑
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐

Relay Equipment Removed

SAP #	IEEE #	CIPS	Manufacturer	Type	Part #	Serial #	Load Shedding Removed	Settings Removed	Event Records Removed	Passwords Removed
380319	11	None	ABB	2000R	587R0462-61110	211344S	☑	☑	☑	☑
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐

Routable Protocol Information

SAP #	IEEE #	Serial #	Ethernet Connection	IP address	Subnet Mask	Default Gateway	IP Port #	MAC Address

*All Protection and Control Relay Equipment Memorandums must be sent to Commissioning@pacificorp.com, including CIPS/Non-CIPS Firmware updates.