

ONEIDA DEVELOPMENT
FLOATING STOP-LOGS INTO PLACE AT GATE NO. 3
AUG. 29, 1917
23184



ONEIDA DEVELOPMENT
LOADING ROCK ON BARGE
AUG. 25, 1917
23185


ONEIDA DEVELOPMENT
LOOKING TOWARD FACE OF DAM
AUG. 25, 1917
23186



ONEIDA DEVELOPMENT
7 SINKING STOP-LOGS IN PLACE OVER
TAINTER GATE OPENING
AUG. 29, 1917
23181


ONEIDA DEVELOPMENT
STOP-LOGS IN PLACE OVER TAINTER
GATE OPENING
AUG. 29, 1917
23182


ONEIDA DEVELOPMENT
5½ POUND TROUT CAUGHT IN TAILRACE
AUG. 27, 1917
23183



ONEIDA DEVELOPMENT
4 SINKING STOP-LOGS IN PLACE OVER
TAINTER GATE OPENING
AUG. 25, 1917
23178


ONEIDA DEVELOPMENT
5 SINKING STOP-LOGS IN PLACE OVER
TAINTER GATE OPENING
AUG. 25, 1917
23179


ONEIDA DEVELOPMENT
6 SINKING STOP-LOGS IN PLACE OVER
TAINTER GATE OPENING
AUG. 29, 1917
23180



ONEIDA DEVELOPMENT
1 SINKING STOP-LOG IN PLACE OVER
TAINTER GATE OPENING
AUG. 25, 1917
23175




ONEIDA DEVELOPMENT
2 SINKING STOP-LOGS IN PLACE OVER
TAINTER GATE OPENING
AUG. 29, 1917
23176




ONEIDA DEVELOPMENT
3 SINKING STOP-LOGS IN PLACE OVER
TAINTER GATE OPENING
AUG. 29, 1917
23177


ONEIDA DEVELOPMENT
DISK HARROW AT WORK ON DIKE
SEPT. 8, 1917
23677


ONEIDA DEVELOPMENT
VIEW OF DIKE FROM EAST
SEPT. 8, 1917
23678


ONEIDA DEVELOPMENT
LOADING WAGONS AT CLAY BORROW PIT
SEPT. 8, 1917
23679


ONEIDA DEVELOPMENT
LOOKING ACROSS DYKE FROM EAST
SEPT. 1, 1917
23655


ONEIDA DEVELOPMENT
GRAVEL PIT
SEPT. 1, 1917
23654


ONEIDA DEVELOPMENT
LOOKING ACROSS DYKE FROM WEST
SEPT. 1, 1917
23653

ONEIDA DEVELOPMENT
PETROLITHIC ROLLER ON DYKE
SEPT. 1, 1917
23638

ONEIDA DEVELOPMENT
BANG PLOW ON DYKE
SEPT. 1, 1917
23639


ONEIDA DEVELOPMENT
DYKE
RUSSELL GRADER AT WORK
SEPT. 1, 1917
23652



ONEIDA DEVELOPMENT
FLOATING STOP-LOGS INTO POSITION FOR
CLOSING TAINTER GATE OPENING
AUG. 25, 1917
23187



ONEIDA DEVELOPMENT
JOHN DEERE DISC PLOW ON DYKE
SEPT. 1, 1917
23636



ONEIDA DEVELOPMENT
RUSSELL ROAD LEVELER ON DYKE
SEPT. 1, 1917
23637


ONEIDA DEVELOPMENT
DIKE.
PLOWING GRAVEL & CLAY
SEPT. 15, 1917
23724


ONEIDA DEVELOPMENT
DUMPING CLAY ON DIKE
SEPT. 15, 1917
23725



ONEIDA DEVELOPMENT
MOTOR-BOAT TOWING BARGE ACROSS LAKE
SEPT. 15, 1917
23726


ONEIDA DEVELOPMENT
SAND BORROW PIT NORTHEAST OF DIKE
SEPT. 8, 1917
23680



ONEIDA DEVELOPMENT
DIKE.
PETROLITHIC ROLLER AT WORK
SEPT. 15, 1917
23722


ONEIDA DEVELOPMENT
DIKE.
DISC-PLOW MIXING GRAVEL AND CLAY
SEPT. 15, 1917
23723


ONEIDA DEVELOPMENT
ROAD LEVELER AT WORK ON DIKE
SEPT. 16, 1917
23730


ONEIDA DEVELOPMENT
SPILLWAY SECTION AT TAINTER-GATES
SEPT. 16, 1917
23731



ONEIDA DEVELOPMENT
DAM.
TOWING TAINTER-GATE TO EAST BANK OF LAKE
SEPT. 21, 1917
23737



ONEIDA DEVELOPMENT
LOOKING ACROSS DIKE FROM EAST
SEPT. 15, 1917
23729



ONEIDA DEVELOPMENT
LOOKING ACROSS DIKE FROM WEST
SEPT. 15, 1917
23728



ONEIDA DEVELOPMENT
DAM
CEMENT HOUSE AND PLATFORM
SEPT. 15, 1917
23727



ONEIDA DEVELOPMENT
GRAVEL PIT FROM WEST
OCT. 2, 1917
23781


ONEIDA DEVELOPMENT
4 IN. PIPE BRIDGE ON DAM
OCT. 1, 1917
23782


ONEIDA DEVELOPMENT
DAM.
LOOKING SOUTH
OCT. 1, 1917
23783


ONEIDA DEVELOPMENT
DAM.
LOADING TAINTER-GATE ON BARGE
SEPT. 21, 1917
23738


ONEIDA DEVELOPMENT
DAM.
DIVER INSPECTING SLUICE-GATES
SEPT. 21, 1917
23739



ONEIDA DEVELOPMENT
PETROLITHIC ROLLER USED ON
DIKE CONSTRUCTION
SEPT. 21, 1917
23742


ONEIDA DEVELOPMENT
DIKE.
VIEW FROM WEST
OCT. 15, 1917
23829


ONEIDA DEVELOPMENT
DAM.
VIEW FROM NORTH
OCT. 15, 1917
23828


ONEIDA DEVELOPMENT
DAM.
VIEW FROM SOUTH
OCT. 15, 1917
23827


ONEIDA DEVELOPMENT
DAM.
LOOKING NORTH
OCT. 1, 1917
23784


ONEIDA DEVELOPMENT
DIKE.
LOOKING WEST
OCT. 1, 1917
23785


ONEIDA DEVELOPMENT
DIKE.
LOOKING EAST
OCT. 1, 1917
23786



ONEIDA DEVELOPMENT
LOOKING NORTH ACROSS DAM
NOV. 1, 1917
23913


ONEIDA DEVELOPMENT
LOOKING WEST ACROSS DIKE
NOV. 1, 1917
23912


ONEIDA DEVELOPMENT
LOOKING EAST ACROSS DIKE
NOV. 1, 1917
23911


ONEIDA DEVELOPMENT
DIKE.
VIEW FROM EAST
OCT. 15, 1917
23830



ONEIDA DEVELOPMENT
GRAVEL PIT FROM SOUTH
OCT. 15, 1917
23831



ONEIDA DEVELOPMENT
SWITCHYARD FROM NORTH
OCT. 15, 1917
23832



ONEIDA DEVELOPMENT
DAM.
VIEW FROM EAST, SHOWING CONCRETE POURING
NOV.19,1917
23967



ONEIDA DEVELOPMENT
DAM.
VIEW FROM SOUTH
NOV.19,1917
23966


ONEIDA DEVELOPMENT
DAM.
SHOWING FORM-WORK FROM NORTH
NOV.19,1917
23965



ONEIDA DEVELOPMENT
LOOKING SOUTH ACROSS DAM
NOV. 1, 1917
23914


ONEIDA DEVELOPMENT
DAM
ROCK-LEDGE AT SOUTH END
NOV. 1, 1917
23915



ONEIDA DEVELOPMENT
SWITCHYARD.
CONCRETING STUBS
NOV. 1, 1917
23916



ONEIDA DEVELOPMENT
DAM FROM WEST.
SHOWING FORM-WORK FOR NEW CONSTRUCTION
DEC. 1, 1917
24030





ONEIDA DEVELOPMENT
DAM FROM S.E.
SHOWING FORM-WORK FOR NEW CONSTRUCTION
DEC. 2, 1917
24031





ONEIDA DEVELOPMENT
SWITCHYARD.
EXCAVATION FOR LIGHTNING ARRESTERS
DEC. 2, 1917
24032



ONEIDA DEVELOPMENT
DAM.
SHOWING FORM-WORK FROM WEST
NOV.19, 1917
23968


ONEIDA DEVELOPMENT
DIKE.
COMPLETED TO ELEV. 4860. VIEW FROM WEST
NOV.19, 1917
23969



ONEIDA DEVELOPMENT
DIKE.
COMPLETED TO ELEV. 4860. VIEW FROM EAST
NOV.19, 1917
23970


ONEIDA DEVELOPMENT
DAM.
VIEW FROM SOUTH
DEC. 15, 1917
24094


ONEIDA DEVELOPMENT
DIKE.
RIPRAP ON UPSTREAM FACE. LOOKING EAST
DEC. 15, 1917
24093


ONEIDA DEVELOPMENT
DAM.
FRONT-VIEW. LOOKING WEST
DEC. 15, 1917
24092


ONEIDA DEVELOPMENT
DAM
LOOKING SOUTH
DEC. 1, 1917
24035


ONEIDA DEVELOPMENT
DAM
LOOKING NORTH
DEC. 1, 1917
24034


ONEIDA DEVELOPMENT
DIKE
PLACING RIPRAP
DEC. 1, 1917
24033




ONEIDA DEVELOPMENT
DIKE.
RIPRAP ON UPSTREAM FACE, LOOKING WEST
JAN. 1, 1918
24132





ONEIDA DEVELOPMENT
DIKE.
RIPRAP ON UPSTREAM FACE, LOOKING EAST
JAN. 1, 1918
24133



ONEIDA DEVELOPMENT
DAM.
VIEW FROM WEST
JAN. 1, 1918
24134


ONEIDA DEVELOPMENT
DAM.
BACK-VIEW. LOOKING EAST
DEC. 15, 1917
24095


ONEIDA DEVELOPMENT
DIKE.
RIPRAP ON UPSTREAM FACE. LOOKING WEST
DEC. 15, 1917
24096


ONEIDA DEVELOPMENT
DAM.
VIEW FROM NORTH
DEC. 15, 1917
24097


ONEIDA DEVELOPMENT
DAM.
DOOR CUT IN SOUTH END OF VALVE CHAMBER
JAN. 16, 1918
24175



ONEIDA DEVELOPMENT
DAM.
LOOKING NORTH ACROSS DAM
JAN. 16, 1918
24174


ONEIDA DEVELOPMENT
DAM.
LOOKING SOUTH ACROSS DAM
JAN. 16, 1918
24173


ONEIDA DEVELOPMENT
DAM.
VIEW FROM EAST
JAN. 1, 1918
24135

ONEIDA DEVELOPMENT
DAM.
LOOKING NORTH ACROSS DAM
JAN. 1, 1918
24136

ONEIDA DEVELOPMENT
HEADWORKS.
SCREENS IN WESTSIDE OF INTAKE
JAN. 16, 1918
24172



ONEIDA DEVELOPMENT
DAM.
LOOKING SOUTH ACROSS DAM
FEB. 1, 1918
24221


ONEIDA DEVELOPMENT
DAM.
BACK OF DAM, LOOKING EAST
FEB. 1, 1918
24222



ONEIDA DEVELOPMENT
DAM.
WALL CONSTRUCTION AT SOUTH END OF DAM
FEB. 1, 1918
24223




ONEIDA DEVELOPMENT
DAM.
BACK OF DAM FROM WEST
JAN. 16, 1918
24176





ONEIDA DEVELOPMENT
DAM.
UPSTREAM FACE FROM EAST
JAN. 16, 1918
24177




ONEIDA DEVELOPMENT
DAM.
FACE OF DAM, LOOKING WEST
FEB. 1, 1918
24220


ONEIDA DEVELOPMENT
DAM.
LOOKING EAST AT BACK OF DAM
MARCH 1, 1918
24248


ONEIDA DEVELOPMENT
DAM.
LOOKING SOUTH ACROSS DAM
MARCH 1, 1918
24249


ONEIDA DEVELOPMENT
DAM.
PROTECTION WALL AT SOUTH END COMPLETED
MARCH 1, 1918
24250




ONEIDA DEVELOPMENT
DAM.
EXCAVATION FOR SLAB AND WALL AT
NORTH END OF DAM
FEB. 1, 1918
24224




ONEIDA DEVELOPMENT
INTAKE.
BRIDGE FROM INTAKE TO DIKE
FEB. 1, 1918
24225




ONEIDA DEVELOPMENT
DIKE.
CYCLONE DRILL DRILLING FOR LOCATION OF
SUPPOSED LEAK IN DIKE
MARCH 1, 1918
24247


ONEIDA DEVELOPMENT
DAM.
PROTECTION SLAB AND WALL AT EAST END
MARCH 15, 1918
24284


ONEIDA DEVELOPMENT
DAM.
PROTECTION SLAB AND WALL AT WEST END
MARCH 15, 1918
24283



ONEIDA DEVELOPMENT
DAM.
LOOKING SOUTH ACROSS DAM
MARCH 15, 1918
24282


ONEIDA DEVELOPMENT
DAM.
PROTECTION WALL AT NORTH END,
VIEW FROM BOTTOM OF DAM
MARCH 1, 1918
24251



ONEIDA DEVELOPMENT
DAM.
PROTECTION WALL AT NORTH END,
VIEW FROM TOP OF DAM
MARCH 1, 1918
24252


ONEIDA DEVELOPMENT
DAM.
LOOKING WEST AT UPSTREAM FACE
MARCH 15, 1918
24281



ONEIDA DEVELOPMENT
DAM.
LOOKING SOUTH ACROSS TOP
APRIL 1, 1918
24315


ONEIDA DEVELOPMENT
DAM.
LOOKING EAST AT BACK OF DAM
APRIL 1, 1918
24316



ONEIDA DEVELOPMENT
DIKE.
SHOWING LEAK IN DIKE, LOOKING NORTH
APRIL 1, 1918
24317


ONEIDA DEVELOPMENT
DAM.
LOOKING EAST AT BACK OF DAM
MARCH 15, 1918
24285


ONEIDA DEVELOPMENT
DIKE.
DRILLING 7th TEST HOLE ON UPSTREAM
FACE OF DIKE
MARCH 15, 1918
24286


ONEIDA DEVELOPMENT
DAM.
PROTECTION WALL AND SLAB AT
EAST END OF DAM
APRIL 1, 1918
24314



ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
JOHNSON VALVE IN PLACE, END VIEW
JAN. 27, 1920
24964


ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
NO. 3 PENSTOCK ERECTION
JAN. 17, 1920
24963


ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
SUBSTRUCTURE LOOKING DOWN FROM 5th FLOOR
JAN. 17, 1920
24962



ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
SUBSTRUCTURE SHOWING STATOR ASSEMBLED
JAN. 17, 1920
24961



ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
JOHNSON VALVE ERECTION
JAN. 17, 1920
24960



ONEIDA DEVELOPMENT
HEADWORKS.
BRIDGE BETWEEN INTAKE & DIKE. LOOKING SOUTH
APRIL 1, 1918
24318



ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
FORMS FOR JOHNSON VALVE CHAMBER
FEB. 15, 1920
24981



ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
PENSTOCK SADDLES NOS. 4 & 5
FEB. 15, 1920
24980



ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
PENSTOCK SADDLES NOS. 1, 2, 3, 4 & 5
FEB. 15, 1920
24979



ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
PENSTOCK ERECTION
JAN. 27, 1920
24965


ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
SUBSTRUCTURE FLOOR FROM UPPER GALLERY
JAN. 27, 1920
24966


ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
JOHNSON VALVE IN PLACE
JAN. 27, 1920
24967


ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
PENSTOCK FROM ABOVE
MAY 1. 1920
31102



Note: End connections not tied together showing inadequate size of spacer blocks
ONEIDA STATION
NO. 2 GENERATOR FAILURE.
SHOWING SPACE BETWEEN END CONNECTIONS
ON OPPOSITE SIDE FROM BREAKDOWN
FEB. 4. 1921
31335


← Rotation
Three coils and iron burned
and
Two adjacent connections
burned in two
ONEIDA STATION
NO. 2 GENERATOR FAILURE.
DETAILS OF BREAKDOWN - BEFORE DISMANTLING
FEB. 4. 1921
31336

ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
THIRD UNIT GENERATOR
MAY 1. 1920
31099


ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
THIRD UNIT BUS STRUCTURE
MAY 1. 1920


ONEIDA DEVELOPMENT
THIRD UNIT INSTALLATION.
PENSTOCK CONSTRUCTION
MAY 1. 1920
31101



Paper inserted in space not filled by spacer blocks
ONEIDA STATION
GENERATOR FAILURE
BETWEEN END CONNECTIONS
NEAR THE LOCATION OF THE BREAKDOWN
FEB. 4, 1921
31340



ONEIDA DEVELOPMENT
GENERAL VIEW OF STATION & 130 KV. SWITCHYARD,
LOOKING EAST
MARCH, 1921
31350


ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
LG-19 AIR SWITCHES ON
TRANSFORMER STRUCTURE
MAR. 17, 1921
31351


Rotation
Iron burned in three slots
Two adjacent end connections burned in two.
ONEIDA STATION
NO. 2 GENERATOR FAILURE.
DETAILS OF BREAKDOWN - WITH THREE TOP BARS REMOVED FROM SLOTS
FEB. 4. 1921
31337


Slight burning on poles
Edges of vernier boards burned
ONEIDA STATION
NO. 2 GENERATOR FAILURE.
DETAILS OF DAMAGE DONE TO ROTOR
FEB. 4. 1921
31338



ONEIDA STATION
NO. 2 GENERATOR FAILURE.
SHOWING BURNING OF THE INSULATION, 1/3 OF DISTANCE AROUND FROM BREAKDOWN
FEB. 4. 1921
31339




ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
LG-19 AIR SWITCH MOUNTED ON
NEW TRANSFER STRUCTURE
MAR. 11, 1921
31355





ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
OIL-SWITCH FOR LINE NO. 3 IN NEW LOCATION
FEB. 1921
31356





ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
EAST SIDE OF YARD AFTER COMPLETION OF
NEW WORK, LOOKING NORTH
MAR. 17, 1921
31357


ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
GENERAL VIEW, LOOKING EAST, AFTER
COMPLETION OF NEW WORK
MAR. 17, 1921
31352



ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
RIVER CROSSING STRUCTURE, SHOWING NEW
GROUNDING DEVICE WITH COUNTERWEIGHT
MAR. 11, 1921
31353


ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
RIVER CROSSING STRUCTURE, SHOWING NEW
GROUNDING DEVICE WITH COUNTERWEIGHT
MAR. 11, 1921
31354


ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
TEMPORARY STRUCTURES TO CLEAR YARD
WHILE MAKING ADDITIONS
JAN. 1921
31361


ONEIDA DEVELOPMENT
LOOKING WEST TOWARD DAM, SHOWING
DIP OF EXPOSED ROCK LEDGE
JUNE 13, 1928
36351


ONEIDA DEVELOPMENT
DAM
WEST ABUTMENT
JULY 20, 1934
36704


ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
TEMPORARY STRUCTURES TO CLEAR YARD
WHILE MAKING ADDITIONS
JAN. 1921
31360


ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
TEMPORARY STRUCTURES TO CLEAR YARD
WHILE MAKING ADDITIONS
JAN. 1921
31359


ONEIDA DEVELOPMENT
130 KV. SWITCHYARD.
TEMPORARY STRUCTURES TO CLEAR YARD
WHILE MAKING ADDITIONS
JAN. 1921
31358




ONEIDA DEVELOPMENT
DAM
TOE OF SPILLWAY SECTION
JULY 20, 1934 36708




No Neg. 36784



ONEIDA DEVELOPMENT
DAM
WEST ABUTMENT
JULY 20, 1934
36705


ONEIDA DEVELOPMENT
DAM
LOOKING UPSTREAM AT EAST ABUTMENT
JULY 20, 1934
36706


ONEIDA DEVELOPMENT
DAM
TOE OF SPILLWAY SECTION
JULY 20, 1934
36707



No Neg. 36787




No Neg. 36788



No Neg. 36786



No Neg. 36785



No Neg. 36789