PACIFICORP

PROTECTION AND CONTROL RELAY EQUIPMENT MEMORANDUM FORM

Version 13

PacifiCorp Relay Technical Services Form PCF-EQP-MEMO

Refer to PacifiCorp Procedure PCP-EQP-MEMO

The person responsible for the completion of this form shall print their name below as verification that the form has been filled out accurately.

Responsible Person: Stephen Emero (PGE) **Phone number:** (801)755-6094 **Date:** 08/08/2022

Equipment Identification

Substation: Lassen Substation	Work Order: 10049825	Relay Package SAP #:90160
Apparatus Equipment/Line Protected:751 CB 5G79 FEEDER #5 BYPASS SWITCH	Bldg/Equip Physical Location: 41.30495,-122.32075	Recloser Controller Battery SI#: NA

Update to Existing Package: ☐	New Package/Upgrade Installation: ☑	CIPS Firmware Update: ☐ *Send to cipmaintrecord@pacificorp.com	Non-CIPS Firmware Update: ☐ *Rocky Mountain Power: Send to RMPAssetmanagement@pacificorp.com *Pacific Power: Send to PP_EquipmentMemorandums@pacificorp.com

Relay Equipment Installed

SAP #	IEEE #	CIPS	Panel #	Manufacturer	Type	Part #	Serial #	Firmware #	Pswd Change	Alm to SCADA	Load Shed	Ext Conn	CIP Sticker	Security Log	Dwgs Chkd
90161	11		1	SEL	751	751501AA06XBA850120	3172070304	SEL-751-R202-V2-Z007003-D20211116	☐	☑	☐		☐	☐	☑
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐

Relay Equipment Removed

SAP #	IEEE #	CIPS	Manufacturer	Type	Part #	Serial #	Load Shedding Removed	Settings Removed	Event Records Removed	Passwords Removed
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐

Routable Protocol Information

SAP #	IEEE #	Serial #	Ethernet Connection	IP address	Subnet Mask	Default Gateway	IP Port #	MAC Address

*All Protection and Control Relay Equipment Memorandums must be sent to Commissioning@pacificorp.com, including CIPS/Non-CIPS Firmware updates.