PACIFICORP

PROTECTION AND CONTROL RELAY EQUIPMENT MEMORANDUM FORM

Version 13

PacifiCorp Relay Technical Services Form PCF-EQP-MEMO

Refer to PacifiCorp Procedure PCP-EQP-MEMO

The person responsible for the completion of this form shall print their name below as verification that the form has been filled out accurately.

Responsible Person: EDWARDS **Phone number:** 541-864-9885 **Date:** 09/14/2021

Equipment Identification

Substation: LITTLE SHASTA	Work Order: 10069562	Relay Package SAP #:448339
Apparatus Equipment/Line Protected: Little Shasta Feeder	Bldg/Equip Physical Location: Little Shasta Sub	Recloser Controller Battery SI#: 7889494

Update to Existing Package: ☐	New Package/Upgrade Installation: ☑	CIPS Firmware Update: ☐ *Send to cipmaintrecord@pacificorp.com	Non-CIPS Firmware Update: ☐ *Rocky Mountain Power: Send to RMPAssetmanagement@pacificorp.com *Pacific Power: Send to PP_EquipmentMemorandums@pacificorp.com

Relay Equipment Installed

SAP #	IEEE #	CIPS	Panel #	Manufacturer	Type	Part #	Serial #	Firmware #	Pswd Change	Alm to SCADA	Load Shed	Ext Conn	CIP Sticker	Security Log	Dwgs Chkd
448339	11	None	6G25	SEL	751	PARTNO=751502CA06XBC850330","06AF"	3202460098	"FID=SEL-751-R300-V3-Z008004-D20210104","08A4"	☑	☑	☐	None	☐	☐	☑
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐
									☐	☐	☐		☐	☐	☐

Relay Equipment Removed

SAP #	IEEE #	CIPS	Manufacturer	Type	Part #	Serial #	Load Shedding Removed	Settings Removed	Event Records Removed	Passwords Removed
307906	50/51	None	GE	IAC -53	12IAC53B11A	NA	☐	☑	☐	☐
307912	50/51	None	GE	IAC -53	12IAC53B11A	NA	☐	☑	☐	☐
307918	50/51N	None	GE	IAC -53	12IAC53B129A	NA	☐	☑	☐	☐
307924	79	None	KELMAN	KSV		NA	☐	☑	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐
							☐	☐	☐	☐

Routable Protocol Information

SAP #	IEEE #	Serial #	Ethernet Connection	IP address	Subnet Mask	Default Gateway	IP Port #	MAC Address

*All Protection and Control Relay Equipment Memorandums must be sent to Commissioning@pacificorp.com, including CIPS/Non-CIPS Firmware updates.