

CalAdvocates Data Request 6.11

The following questions relate to your 2023-2025 WMP submission.

If a full response to a given question will be included in your WMP submission, your response to that question of this data request may consist of a citation to the specific page(s) or table(s) of the WMP where the information may be found, a written response to the question, or both.

Ignitions

Identify any ignitions in 2022 associated with assets where you had an existing corrective notification at the time of the ignition. Please provide a spreadsheet listing each such ignition (as rows) with the following information in separate columns:

- (a) Unique ignition ID
- (b) Date of ignition
- (c) Cause of ignition
- (d) Type of asset associated with the ignition
- (e) Acres burned
- (f) Number of structures burned, if any
- (g) Number of injuries associated with ignition, if any
- (h) Asset ID of asset associated with ignition
- (i) Circuit ID number of circuit associated with ignition
- (j) Notification number(s) for the existing maintenance tag on the asset in question.
- (k) Priority level of the existing corrective notification on the asset in question

Response to CalAdvocates Data Request 6.11

Please refer to Attachment CalAdvocates 6.11.

Unique ignition ID	Date of ignition	Cause of ignition	Type of asset associated with the ignition	Acres burned	Number of structures burned, if any	Number of injuries associated with ignition, if any	Asset ID of asset associated with ignition	Circuit ID number of circuit associated with ignition	Notification number(s) for the existing maintenance tag on the asset in question.	Priority level of the existing corrective notification on the asset in question
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-DETAIL-04_16_2019-GO95MLD-1	B
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-DETAIL-04_23_2014-COTELINS-1	B
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-AUDIT-12_21_2009-CLRTELCO-1	C
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-DTLTRT-10_26_2009-GO95MLD-1	C
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-DETAIL-12_28_2004-BOGUYANC-1	B
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-DETAIL-12_28_2004-BOGUYANC-2	B
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-DETAIL-12_28_2004-BOGUYANC-3	B
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-DETAIL-12_28_2004-CLRTELCO-1	B
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-DETAIL-12_28_2004-CLRTV-1	B
06252022 - Altruas	6/25/2022	Contact	Object OH Service Wire	<0.25	0	0	0	10048133 5L86	786217613-9429-DETAIL-12_28_2004-CLRTV-2	B
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DETAIL-03_07_2022-GO95MLD-1	B
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DETAIL-03_07_2022-GUYHINS-1	B
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DETAIL-01_19_2017-GO95HV-1	C
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DETAIL-01_19_2017-UNIGRDSG-1	B
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DETAIL-04_02_2012-BOUNIGRD-1	C
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DETAIL-04_02_2012-GO95MLD-1	C
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DTLTRT-10_22_2007-BOGRDBND-1	B
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DTLTRT-10_22_2007-BOGRDBND-2	B
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DTLTRT-10_22_2007-BOGRDBND-3	B
07032022 - Tulelake	7/3/2022	Contact	Object POLE OH	Unknown	0	0	0 820	TR_084700_1890018 5L68	508828931-20361-DTLTRT-10_22_2007-COOTHER-1	B
07142022 - Yreka	7/14/2022	3rd Party	Unknown-3rd Party Unknown-3rd Party	Unknown-3rd Party	0	0	0	-	-	-
07272022 - Hornbrook	7/27/2022	Contact	Object POLE OH	1/2 acre	0	0	0 684	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180 5G19	64495098-2813-DETAIL-01_27_2015-COTELGUY-1	B
07272022 - Hornbrook	7/27/2022	Contact	Object POLE OH	1/2 acre	0	0	0 684	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180 5G19	64495098-2813-DETAIL-01_27_2015-GUYSLACK-1	B
07272022 - Hornbrook	7/27/2022	Contact	Object POLE OH	1/2 acre	0	0	0 684	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180 5G19	64495098-2813-DTLTRT-10_21_2010-BOGUYANC-1	C
07272022 - Hornbrook	7/27/2022	Contact	Object POLE OH	1/2 acre	0	0	0 684	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180 5G19	64495098-2813-DTLTRT-10_21_2010-COTELCO-1	C
07272022 - Hornbrook	7/27/2022	Contact	Object POLE OH	1/2 acre	0	0	0 684	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180 5G19	64495098-2813-ADMIN-11_16_2007-BOGUYANC-1	C
07272022 - Hornbrook	7/27/2022	Contact	Object POLE OH	1/2 acre	0	0	0 684	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180 5G19	64495098-2813-ADMIN-11_15_2007-BOGUYANC-1	B
07272022 - Hornbrook	7/27/2022	Contact	Object POLE OH	1/2 acre	0	0	0 684	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180 5G19	64495098-2813-ADMIN-11_14_2007-GO95HV-1	C
07272022 - Hornbrook	7/27/2022	Contact	Object POLE OH	1/2 acre	0	0	0 684	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180 5G19	64495098-2813-DETAIL-11_14_2007-BOGUYANC-2	B
07272022 - Hornbrook	7/27/2022	Contact	Object POLE OH	1/2 acre	0	0	0 684	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180 5G19	64495098-2813-DETAIL-11_14_2007-BOGUYANC-1	B

07272022 - Hornbrook	7/27/2022	Contact	Object	POLE OH	1/2 acre	0	0	684	5G19	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180	64495098-2813-DETAIL-11_14_2007-BOXARM-1	B
07272022 - Hornbrook	7/27/2022	Contact	Object	POLE OH	1/2 acre	0	0	684	5G19	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180	64495098-2813-DETAIL-11_14_2007-COOTHER-1	B
07272022 - Hornbrook	7/27/2022	Contact	Object	POLE OH	1/2 acre	0	0	684	5G19	RC_270861_1910535 238 TR_296980_1910192 616 TR_176002_1910180 684 TR_176002_1910180	64495098-2813-DETAIL-11_14_2007-TREETRIM-1	B
07292022 - Klamath River	7/29/2022	Unknown	Unknown	Unknown	61,000	Unknown	Unknown	Unknown	Unknown	Unknown	Unknown	Unknown
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-57170-DTLTRT-05_17_2021-BIRDDMG-1		B
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-67690-DTLTRT-05_14_2021-BIRDDMG-1		B
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-67690-DETAIL-03_26_2020-BIRDDMG-1		C
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-57170-DETAIL-06_21_2016-GO95HV-1		C
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-67690-DETAIL-06_21_2016-BIRDDMG-1		B
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-67690-DETAIL-06_21_2016-GO95HV-1		C
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-57170-DETAIL-10_15_2014-GO95MLD-1		C
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-67690-DETAIL-10_15_2014-BIRDDMG-1		B
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-67690-DETAIL-10_15_2014-BOGUYANC-1		B
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-67690-DETAIL-02_28_2012-CLEAR-1		B
07312022 - Castella	7/31/2022	Contact	Object	NO DISTRIBUTION DAMAGE	1/2 acre	0	0	CLA_CB8G65	8G65	731364769-57170-DETAIL-07_15_2009-COOTHER-1		C
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-10_17_2022-BIRDDMG-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-10_17_2022-GO95HV-1		C
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-10_17_2022-GO95MLD-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-10_17_2022-GO95MLD-2		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-10_17_2022-GO95MLD-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-06_14_2017-UNIGRDSG-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-02_08_2012-BIRDDMG-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-02_08_2012-BOUNIGRD-1		C
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-02_08_2012-GO95MLD-1		C
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-ADMIN-10_18_2007-BOGRDBND-1		C
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-ADMIN-10_17_2007-BOGUYANC-1		C
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DTLTRT-10_17_2007-BIRDDMG-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DTLTRT-10_17_2007-BOGRDBND-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DTLTRT-10_17_2007-BOGUYANC-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DTLTRT-10_17_2007-CLRTELCO-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DTLTRT-10_17_2007-TREETRIM-1		B
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DETAIL-08_24_1998-CLRTELCO-1		C
08072022 - Horse Creek	8/7/2022	Contact	Object	POLE OH	Unknown	0	0	LineCut - 142582	5G40	402513510-42289-DTLTRT-08_24_1998-COOTHER-2		B
08112022 - Scott Bar	8/11/2022	Contact	Environment/object	NO DISTRIBUTION DAMAGE	25 acres	0	0	8071	5G40	TR_323600_1910058 016 OH_316300_191005	348172454-92109-DETAIL-10_25_2022-GO95HV-1	C
08112022 - Scott Bar	8/11/2022	Contact	Environment/object	NO DISTRIBUTION DAMAGE	25 acres	0	0	8071	5G40	TR_323600_1910058 016 OH_316300_191005	348172454-92109-DETAIL-02_13_2012-GO95GUYS-1	C
08112022 - Scott Bar	8/11/2022	Contact	Environment/object	NO DISTRIBUTION DAMAGE	25 acres	0	0	8071	5G40	TR_323600_1910058 016 OH_316300_191005	348172454-92109-DETAIL-02_13_2012-GO95HV-1	C
08112022 - Scott Bar	8/11/2022	Contact	Environment/object	NO DISTRIBUTION DAMAGE	25 acres	0	0	8071	5G40	TR_323600_1910058 016 OH_316300_191005	348172454-92109-ADMIN-10_28_2007-COOTHER-1	B
08112022 - Scott Bar	8/11/2022	Contact	Environment/object	NO DISTRIBUTION DAMAGE	25 acres	0	0	8071	5G40	TR_323600_1910058 016 OH_316300_191005	348172454-92109-ADMIN-10_27_2007-BOGUYANC-1	C
08112022 - Scott Bar	8/11/2022	Contact	Environment/object	NO DISTRIBUTION DAMAGE	25 acres	0	0	8071	5G40	TR_323600_1910058 016 OH_316300_191005	348172454-92109-ADMIN-10_26_2007-BOGUYANC-1	C
08112022 - Scott Bar	8/11/2022	Contact	Environment/object	NO DISTRIBUTION DAMAGE	25 acres	0	0	8071	5G40	TR_323600_1910058 016 OH_316300_191005	348172454-92109-DTLTRT-10_26_2007-BOGUYANC-1	B
08112022 - Scott Bar	8/11/2022	Contact	Environment/object	NO DISTRIBUTION DAMAGE	25 acres	0	0	8071	5G40	TR_323600_1910058 016 OH_316300_191005	348172454-92109-DTLTRT-10_26_2007-BOGUYANC-2	B

08112022 - Scott Bar	8/11/2022	Environment/object contact	NO DISTRIBUTION DAMAGE	25 acres	0	TR_323600_1910058 016 OH_316300_191005 0 8071 5G40	348172454-92109-DTLTRT-10_26_2007-COOTHER-1	B
08112022 - Scott Bar	8/11/2022	Environment/object contact	NO DISTRIBUTION DAMAGE	25 acres	0	TR_323600_1910058 016 OH_316300_191005 0 8071 5G40	348172454-92109-DTLTRT-10_26_2007-COTELCO-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	841301639-35633-DETAIL-02_07_2018-COTELINS-1	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	841301639-35633-DETAIL-02_07_2018-COTELINS-2	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	841301639-35633-DETAIL-02_07_2018-GRDRODHI-1	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	841301639-35633-DTLTRT-10_09_2008-BOGRDBND-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	841301639-35633-DTLTRT-10_09_2008-GO95 CLR-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	841301639-35633-DTLTRT-10_09_2008-GO95 MLD-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	841301639-35633-DTLTRT-10_09_2008-GO95BOHV-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	841301639-35633-DETAIL-03_21_2006-COTELCO-1	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	841301639-35633-DTLTRT-10_06_1999-COOTHER-1	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	859864149-75549-DETAIL-03_14_2023-GO95MLD-1	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	859864149-75549-DETAIL-03_04_2013-GO95MLD-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	859864149-75549-ADMIN-11_07_2008-BOPOLE-1	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	859864149-75549-DTLTRT-10_09_2008-BOPOLE-1	A
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	859864149-75549-DTLTRT-10_09_2008-GO95 MLD-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	859864149-75549-DTLTRT-10_09_2008-GO95 MLD-2	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	859864149-75549-DTLTRT-10_09_2008-GO95BOCN-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	859864149-75549-DTLTRT-10_09_2008-GO95BOHV-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	551375749-55549-DETAIL-03_14_2023-COTELINS-1	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	551375749-55549-DETAIL-02_02_2018-COTELINS-1	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	551375749-55549-DETAIL-03_04_2013-BOXARM-1	B
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	551375749-55549-DTLTRT-10_09_2008-CLRTELCO-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	551375749-55549-DTLTRT-10_09_2008-CLRTELCO-2	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	551375749-55549-DTLTRT-10_09_2008-COTELCO-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	551375749-55549-DTLTRT-10_09_2008-GO95 CLR-1	C
08262022 - Gasquet	8/26/2022	Environment	NO DISTRIBUTION DAMAGE	<0.25	0	TR_211102_1900016 0 504 5R96	551375749-55549-DTLTRT-10_09_2008-GO95BOCN-1	C
09022022 - Weed	9/2/2022	Customer Equipment/3rd Party	POLE OH	Unknown	0	0 LineCut - 143146 5G83	763330503-27051-DETAIL-05_12_2022-GO95MLD-1	B
09022022 - Weed	9/2/2022	Customer Equipment/3rd Party	POLE OH	Unknown	0	0 LineCut - 143146 5G83	763330503-27051-DTLTRT-05_02_2012-GO95BLTC-1	C
09022022 - Weed	9/2/2022	Customer Equipment/3rd Party	POLE OH	Unknown	0	0 LineCut - 143146 5G83	763330503-27051-DTLTRT-05_02_2012-GO95CN-1	C
09022022 - Weed	9/2/2022	Customer Equipment/3rd Party	POLE OH	Unknown	0	0 LineCut - 143146 5G83	763330503-27051-DTLTRT-05_02_2012-GO95MLD-1	C
09022022 - Weed	9/2/2022	Customer Equipment/3rd Party	POLE OH	Unknown	0	0 LineCut - 143146 5G83	763330503-27051-DETAIL-09_14_2009-BOXFRMR-1	A
09022022 - Weed	9/2/2022	Customer Equipment/3rd Party	POLE OH	Unknown	0	0 LineCut - 143146 5G83	763330503-27051-ADMIN-12_04_2007-COOTHER-1	C
09022022 - Weed	9/2/2022	Customer Equipment/3rd Party	POLE OH	Unknown	0	0 LineCut - 143146 5G83	763330503-27051-DETAIL-12_04_2007-COOTHER-1	B
09022022 - Weed	9/2/2022	Customer Equipment/3rd Party	POLE OH	Unknown	0	0 LineCut - 143146 5G83	763330503-27051-DETAIL-03_21_2007-BOXFRMR-1	B
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-06_01_2022-GO95CL10-1	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-06_01_2022-RISECLMB-1	A
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-04_05_2017-BORISER-1	A
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-04_05_2017-COTELINS-1	B
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-04_05_2017-GO95MLD-1	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DTLTRT-05_24_2012-CLRTELCO-1	B
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DTLTRT-05_24_2012-GO95 CLR-1	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DTLTRT-05_24_2012-GO95 MLD-1	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DTLTRT-05_24_2012-GO95BOCN-1	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DTLTRT-05_24_2012-GO95TLCO-1	B
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-10_12_2009-BIRDDMG-1	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-10_12_2009-BOGRDBND-1	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-10_12_2009-COOTHER-1	B
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-10_12_2009-COTELCO-2	B
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-10_12_2009-COTELCO-4	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-10_12_2009-COTELCO-1	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-10_12_2009-COTELCO-3	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0 Unknown Unknown	425890033-91021-DETAIL-10_12_2009-GO95BOHV-1	C

09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0	Unknown	Unknown	425890033-91021-DETAIL-10_12_2009-GO95TLCO-1	C
09052022 - Weed	9/5/2022	Unknown	Unknown	Unknown	0	0	Unknown	Unknown	425890033-91021-DTLTRT-11_04_2003-BOGRDBND-1	B
09102022 - Dorris	9/10/2022	Equipment Failure	POLE OH	<0.25	0	0	C-7802	5L62	458140691-29221-DETAIL-03_18_2015-GO95HV-1	C
09102022 - Dorris	9/10/2022	Equipment Failure	POLE OH	<0.25	0	0	C-7802	5L62	458140691-29221-DETAIL-03_18_2015-GO95MLD-1	B
09102022 - Dorris	9/10/2022	Equipment Failure	POLE OH	<0.25	0	0	C-7802	5L62	458140691-29221-DTLTRT-10_21_2010-GO95 MLD-1	C
09102022 - Dorris	9/10/2022	Equipment Failure	POLE OH	<0.25	0	0	C-7802	5L62	458140691-29221-DETAIL-01_06_2003-COOTHER-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-07_06_2022-SVCFELFC-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-05_30_2017-BIRDDMG-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-05_30_2017-GO95BOHV-1	C
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-02_17_2015-BOPOLE-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-01_31_2012-BIRDDMG-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-01_31_2012-BOUNIGRD-1	C
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-01_31_2012-CLRTELCO-2	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-01_31_2012-CLRTELCO-1	C
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-01_31_2012-CUSTRESP-1	C
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-01_31_2012-GO95 MLD-1	C
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DETAIL-01_31_2012-RWENRCH-1	C
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-ADMIN-03_17_2009-BOGRDBND-1	C
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-ADMIN-03_16_2009-BOGUYANC-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-ADMIN-03_15_2009-COOTHER-1	C
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-BIRDDMG-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-BOGRDBND-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-BOGUYANC-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-CLRTELCO-2	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-COOTHER-2	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-COOTHER-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-CTELMID-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-CTELPOLE-3	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-CUSTRESP-1	B
10202022 - Yreka CA	#####	Party	NO DISTRIBUTION DAMAGE	0.26-9.99	1-3rd Party Structure		OH_140501_191007 0 1193	5G16	304339149-9989-DTLTRT-10_17_2007-TREETRIM-1	B