


— 11-4-2011 WATER SURFACE



CONDIT DAM DECOMMISSIONING		Sheet
WHITE SALMON RIVER 2011 PHOTO POINT LOCATIONS		1
		of
Scale: 1" = 500 ft		1
12-15-2011		



Photo Point #1 Looking Downstream 10.26.11




Photo Point #1 Looking Downstream 10.27.11



Photo Point #12 Looking Downstream 11.10.11



Photo Point #12 Looking Downstream 11.17.11



Photo Point #12 Looking Downstream 11.30.11



Photo Point #12 Looking Downstream 12.08.11



Photo Point #12 Looking Downstream 12.15.11



Photo Point #12 Looking Upstream 11.10.11



Photo Point #12 Looking Upstream 11.17.11



Photo Point #12 Looking Upstream 11.30.11



Photo Point #12 Looking Upstream 12.08.11



Photo Point #12 Looking Upstream 12.15.11



Photo Point #11 Looking Downstream 10.27.11



Photo Point #11 Looking Downstream 10.28.11



Photo Point #11 Looking Downstream 10.30.11



Photo Point #11 Looking Downstream 10.31.11



Photo Point #11 Looking Downstream 11.01.11



Photo Point #11 Looking Downstream 11.10.11



Photo Point #11 Looking Downstream 11.17.11



Photo Point #11 Looking Downstream 11.30.11



Photo Point #11 Looking Downstream 12.08.11 (Significant reservoir erosion ceased)



Photo Point #11 Looking Upstream 10.28.11



Photo Point #11 Looking Upstream 10.30.11



Photo Point #11 Looking Upstream 10.31.11



Photo Point #11 Looking Upstream 11.01.11



Photo Point #11 Looking Upstream 11.03.11



Photo Point #11 Looking Upstream 11.10.11



Photo Point #11 Looking Upstream 11.17.11



Photo Point #11 Looking Upstream 11.30.11



Photo Point #11 Looking Upstream 12.08.11



Photo Point #10 Looking Downstream 10.28.11



Photo Point #10 Looking Downstream 11.03.11



Photo Point #10 Looking Downstream 11.10.11



Photo Point #10 Looking Downstream 11.17.11



Photo Point #10 Looking Downstream 11.30.11 (Significant reservoir erosion ceased)



Photo Point #10 Looking Upstream 11.01.11



Photo Point #10 Looking Upstream 11.03.11



Photo Point #10 Looking Upstream 11.10.11



Photo Point #10 Looking Upstream 11.17.11



Photo Point #10 Looking Upstream 11.30.11 (Significant reservoir erosion ceased)



Photo Point #9 Looking Downstream 10.26.11



Photo Point #9 Looking Downstream 10.27.11



Photo Point #9 Looking Downstream 10.28.11



Photo Point #9 Looking Downstream 10.29.11



Photo Point #9 Looking Downstream 10.30.11



Photo Point #9 Looking Downstream 10.31.11



Photo Point #9 Looking Downstream 11.01.11



Photo Point #9 Looking Downstream 11.03.11



Photo Point #9 Looking Downstream 11.10.11 (Significant reservoir erosion ceased)



Photo Point #9 Looking Upstream 10.26.11



Photo Point #9 Looking Upstream 10.27.11



Photo Point #9 Looking Upstream 10.28.11



Photo Point #9 Looking Upstream 10.29.11



Photo Point #9 Looking Upstream 10.30.11



Photo Point #9 Looking Upstream 10.31.11



Photo Point #9 Looking Upstream 11.01.11



Photo Point #9 Looking Upstream 11.03.11



Photo Point #9 Looking Upstream 11.10.11



Photo Point #9 Looking Upstream 11.17.11



Photo Point #9 Looking Upstream 11.30.11



Photo Point #9 Looking Upstream 12.08.11



Photo Point #7 Looking Upstream 10.26.11



Photo Point #7 Looking Upstream 10.26.11



Photo Point #7 Looking Upstream 10.28.11



Photo Point #7 Looking Upstream 10.29.11



Photo Point #7 Looking Upstream 10.30.11



Photo Point #7 Looking Upstream 10.31.11



Photo Point #7 Looking Upstream 11.01.11



Photo Point #7 Looking Upstream 11.03.11



Photo Point #7 Looking Upstream 11.10.11



Photo Point #7 Looking Upstream 11.17.11



Photo Point #7 Looking Upstream 11.30.11 (Significant reservoir erosion ceased)



Photo Point #6 Looking Upstream 10.26.11



Photo Point #6 Looking Upstream 10.26.11



Photo Point #6 Looking Upstream 10.28.11



Photo Point #6 Looking Upstream 10.29.11



Photo Point #6 Looking Upstream 10.30.11



Photo Point #6 Looking Upstream 10.31.11



Photo Point #6 Looking Upstream 11.01.11



Photo Point #6 Looking Upstream 11.03.11



Photo Point #6 Looking Upstream 11.10.11



Photo Point #6 Looking Upstream 11.30.11



Photo Point #6 Looking Upstream 12.08.11 (Significant reservoir erosion ceased)



Photo Point #5 Looking Downstream 10.26.11



Photo Point #5 Looking Downstream 10.26.11



Photo Point #5 Looking Downstream 10.27.11



Photo Point #5 Looking Downstream 10.28.11



Photo Point #5 Looking Downstream 10.29.11



Photo Point #5 Looking Downstream 10.30.11



Photo Point #5 Looking Downstream 10.31.11



Photo Point #5 Looking Downstream 11.01.11



Photo Point #5 Looking Downstream 11.03.11



Photo Point #5 Looking Downstream 11.17.11 (Significant reservoir erosion ceased)



Photo Point #5 Looking Upstream 10.26.11



Photo Point #5 Looking Upstream 10.26.11



Photo Point #5 Looking Upstream 10.27.11



Photo Point #5 Looking Upstream 10.28.11



Photo Point #5 Looking Upstream 10.29.11



Photo Point #5 Looking Upstream 10.30.11



Photo Point #5 Looking Upstream 10.31.11



Photo Point #5 Looking Upstream 11.01.11



Photo Point #5 Looking Upstream 11.03.11



Photo Point #5 Looking Upstream 11.10.11



Photo Point #5 Looking Upstream 11.17.11



Photo Point #5 Looking Upstream 11.30.11



Photo Point #5 Looking Upstream 12.08.11



Photo Point #4 Looking Downstream 10.26.11



10.26.2011 00:36

Photo Point #4 Looking Downstream 10.26.11



Photo Point #4 Looking Downstream 10.27.11



Photo Point #4 Looking Downstream 10.28.11



Photo Point #4 Looking Downstream 10.29.11



Photo Point #4 Looking Downstream 10.30.11



Photo Point #4 Looking Downstream 10.31.11



Photo Point #4 Looking Downstream 11.01.11



Photo Point #4 Looking Downstream 11.03.11



Photo Point #4 Looking Downstream 11.10.11



Photo Point #4 Looking Downstream 11.17.11




Photo Point #4 Looking Downstream 11.30.11




Photo Point #4 Looking Downstream 12.08.11



Photo Point #4 Looking Upstream 10.26.11



Photo Point #4 Looking Upstream 10.26.11



Photo Point #4 Looking Upstream 10.27.11



Photo Point #4 Looking Upstream 10.28.11



Photo Point #4 Looking Upstream 10.29.11



Photo Point #4 Looking Upstream 10.30.11



Photo Point #4 Looking Upstream 10.31.11



Photo Point #4 Looking Upstream 11.01.11



Photo Point #4 Looking Upstream 11.03.11



Photo Point #4 Looking Upstream 11.10.11



Photo Point #4 Looking Upstream 11.17.11



11/30/2011 13:47

Photo Point #4 Looking Upstream 11.30.11



12/08/2011 13:06

Photo Point #4 Looking Upstream 12.08.11 (Significant reservoir erosion ceased)



Photo Point #3 Looking Downstream 10.26.11



10.26.2011 01:06

Photo Point #3 Looking Downstream 10.26.11



Photo Point #3 Looking Downstream 10.27.11



Photo Point #3 Looking Downstream 10.28.11



Photo Point #3 Looking Downstream 10.29.11



Photo Point #3 Looking Downstream 10.30.11



Photo Point #3 Looking Downstream 10.31.11



Photo Point #3 Looking Downstream 11.01.11



Photo Point #3 Looking Downstream 11.03.11



Photo Point #3 Looking Downstream 11.10.11



Photo Point #3 Looking Downstream 11.17.11



Photo Point #3 Looking Downstream 11.30.11



Photo Point #3 Looking Downstream 12.08.11 (Significant reservoir erosion ceased)



Photo Point #3 Looking Upstream 10.26.11



Photo Point #3 Looking Upstream 10.26.11



Photo Point #3 Looking Upstream 10.27.11



Photo Point #3 Looking Upstream 10.28.11



Photo Point #3 Looking Upstream 10.29.11



Photo Point #3 Looking Upstream 10.30.11



Photo Point #3 Looking Upstream 10.31.11



Photo Point #3 Looking Upstream 11.01.11



Photo Point #3 Looking Upstream 11.03.11



Photo Point #3 Looking Upstream 11.10.11



Photo Point #3 Looking Upstream 11.17.11



Photo Point #3 Looking Upstream 11.30.11



Photo Point #3 Looking Upstream 12.08.11 (Significant reservoir erosion ceased)



Photo Point #2 Looking Downstream 10.26.11



Photo Point #2 Looking Downstream 10.26.11



Photo Point #2 Looking Downstream 10.27.11



Photo Point #2 Looking Downstream 10.28.11



Photo Point #2 Looking Downstream 10.29.11 (photo point moved due to unstable slope)



Photo Point #2 Looking Downstream 10.30.11



Photo Point #2 Looking Downstream 10.31.11



Photo Point #2 Looking Downstream 11.01.11



Photo Point #2 Looking Downstream 11.03.11



Photo Point #2 Looking Downstream 11.10.11



Photo Point #2 Looking Downstream 11.17.11



Photo Point #2 Looking Downstream 11.30.11



Photo Point #2 Looking Downstream 12.08.11



Photo Point #2 Looking Upstream 10.26.11



10.26.2011 04:35

Photo Point #2 Looking Upstream 10.26.11



Photo Point #2 Looking Upstream 10.27.11



Photo Point #2 Looking Upstream 10.28.11



Photo Point #2 Looking Upstream 10.29.11



Photo Point #2 Looking Upstream 10.30.11



Photo Point #2 Looking Upstream 10.31.11



Photo Point #2 Looking Upstream 11.01.11



Photo Point #2 Looking Upstream 11.03.11



Photo Point #2 Looking Upstream 11.10.11



Photo Point #2 Looking Upstream 11.17.11



Photo Point #2 Looking Upstream 11.30.11



Photo Point #2 Looking Upstream 12.08.11



Photo Point #1 Looking Downstream 10.28.11



Photo Point #1 Looking Downstream 10.29.11



Photo Point #1 Looking Downstream 10.30.11



Photo Point #1 Looking Downstream 10.31.11



Photo Point #1 Looking Downstream 11.01.11



Photo Point #1 Looking Downstream 11.03.11



Photo Point #1 Looking Downstream 11.10.11



Photo Point #1 Looking Downstream 11.17.11



Photo Point #1 Looking Downstream 11.30.11



Photo Point #1 Looking Downstream 12.08.11



Photo Point #1 Looking Downstream 12.15.11



Photo Point #1 Looking Upstream 10.28.11



Photo Point #1 Looking Upstream 10.29.11



Photo Point #1 Looking Upstream 10.30.11



Photo Point #1 Looking Upstream 10.31.11



Photo Point #1 Looking Upstream 11.01.11



Photo Point #1 Looking Upstream 11.03.11



Photo Point #1 Looking Upstream 11.10.11



Photo Point #1 Looking Upstream 11.17.11



Photo Point #1 Looking Upstream 11.30.11



Photo Point #1 Looking Upstream 12.08.11



Photo Point #1 Looking Upstream 12.15.11